

# FITNESS CERTIFICATE

To be filed by the Inspecting Officer (Asst. Engineer)

(Re: G.O. Ms. 20/70/ PWD Dt. 23 - 01 -1970)

1. Name of the Officer VINOJ. T. J. (Assistant Engineer)
2. Name of the School Manappuram Geetha Ravi Public
3. Location with name of Education District/ Sub. District Chavakad / Valapad school
4. Classification of Building as specified in column 4 of the application for fitness certificate and size.  
RCC framed structure Building  
Gr.F Area - 145.42 m<sup>2</sup> (436.26 m<sup>2</sup>)  
FF Area - 145.42 m<sup>2</sup>  
SF Area - 145.42 m<sup>2</sup>
5. Period for which the certificate is issued 2026-2027 (up to 31/03/2027)
6. Nature of defects, if any  
a) Foundation and basement  
b) Superstructure  
c) Doors and Windows  
d) Wood work wrought and put up  
e) Roof  
f) Flooring  
g) Miscellaneous (Cracks, etc.)  
NIL
7. Any major defects noticed which will render the building unsafe in any manner  
NIL
8. Whether maintenance works have been done properly Yes
9. Whether the structure is sound or not for conducting classes The structure is found sound for conducting classes under normal wind and weather

**Note : 1. The stability of the structure should be examined also with reference to location, altitude, intensity of wind, conditions exposure of flood etc. 2. Any additional observations if deemed necessary for the certificate may be furnished separately with this certificate.**

**Note:** This certificate is applicable only to safety related to civil constructions. Separate certificate for fire safety and safety of electrical installations electrical lines/conduits departments. Internal wiring of the school should be verified by a Registered/ approved electrician before conducting classes. CERTIFICATE shall be obtained from concerned certified that the school building was inspected by me on 30/05/2026 and

found to be fit / unfit to conduct classes, for the period 2026-2027 (up to 31/03/2027) for the reasons stated above.

**Note:-** Maintenance of school premises should be done periodically. The inspecting officer is not liable for any unfortunate accidents in the school premises due to lack of security or periodic maintenance.

Place: Valapad  
Date: 30/05/2026

(Seal)



VINOJ. T. J.  
PEN No. 703276  
Assistant Engineer  
LSGD (LID & EW) SECTION  
VALAPAD GRAMA PANCHAYATH

# FITNESS CERTIFICATE


To be filled by the Inspecting Officer (Asst. Engineer)  
(Re: G.O. Ms. 20/70/PWD Dt. 23-01-1970)

1. Name of the Officer  
VINOJ. T. J.
  2. Name of the School  
Manappuram Geetha Ravi Public School
  3. Location with name of Education District/ Sub. District  
Valapad, Thrissur
  4. Classification of Building as specified in column 4 of the application for fitness certificate and size.  
Permanent RCC structure  
3 storied single building.  
Details of building is separately attached.
  5. Period for which the certificate is issued  
2026-2027 (up to 31/03/2027)
  6. Nature of defects, if any
    - a) Foundation and basement
    - b) Superstructure
    - c) Doors and Windows
    - d) Wood work wrought and put up
    - e) Roof
    - f) Flooring
    - g) Miscellaneous (Cracks, etc.)NIL
  7. Any major defects noticed which will render the building unsafe in any manner  
NIL
  8. Whether maintenance works have been done properly  
Yes
  9. Whether the structure is sound or not for conducting classes  
structure is found to be sound under normal wind and weather conditions.
- Note :** 1. The stability of the structure should be examined also with reference to location, altitude, intensity of wind, exposure of flood etc. 2. Any additional observations if deemed necessary for the certificate may be furnished separately with this certificate.
- Note :** - This certificate is applicable only to safety related to civil construction. Separate certificate for fire safety and safety of electrical installations electrical lines/conduits shall be obtained from concerned departments. Internal wiring of the school should be verified by a Registered/Approved electrician before conducting classes certified that the school building was inspected by me on 30/05/2026 and
- found to be fit / unfit to conduct classes, for the period 2026-2027 (up to 31/03/2027) for the reasons stated above.
- Note :-** Maintenance of the school premises should be done periodically. The inspecting officer is not liable for any unfortunate accidents in the school premises due to lack of security or periodic maintenance.

Place: Valapad  
Date: 30/05/2026

(Seal)

*[Signature]*



Assistant Engineer  
VINOJ. T. J  
PEN No: 703276  
ASSISTANT ENGINEER  
LSGD (LID & EW) SECTION  
VALAPAD GRAMAPANCHAYATH

**Area Statement of Main Building**  
**Manappuram Geetha Ravi Public School (MaGeet Public School)**

Valappad, Triprayar, Kerala, Kerala 680567

**Ground Floor:-**

Class Rooms	6 mts	x	6 mts	3no's
Class Rooms	6.6	x	12.55	1 no's
Administrative Office	911	x	4	1 no's
Head Master's Office	6.4	x	4	1 no's
Dining Room	6	x	4	1no's
Kitchen	4.72	x	3.8	1no's
pantry	3.1	x	3.8	1no's

Porch, Waiting Area, Toilet block, Staircases, Lift, Verandahs...etc

Total Area of Ground Floor:-771.743 Sqm

**First Floor:-**

Class Rooms	6mts	x	6 mts	2 no's
Class Room	6	x	10.2	1 no's
Class Room	6.6	x	12.55	1no's
Staff Room-				
Female	4.85	x	4	1no's
Staff Room-male	6.4	x	4	1no's
Infirmary Room	5.72	x	3.8	1no's

Porch, Store, Lobby, Toilet block, Staircases, Lift, Verandahs, Balconys... etc

Total Area of First Floor-594.340 Sqm

**Second Floor:-**

Class Rooms	6 mts	x	6mts	2no:s
Class Room	6	x	10.2	1no:s
Class Room	6.6	x	8.55	1no's
Computer Lab	6.4	x	4	1no's
Library	5.72	x	3.8	1no's

Porch, Store, Lobby, Toilet block, Staircases, Lift, Verandahs, Balconys...etc

Total Area of Second Floor-512.086 Sqm

**Terrace floor Area 54.569 Sqm**

**Total Built-up area school main building 1932.738 Sqm**

  
**VINOJ. T.J**  
 PEN No: 703276  
 ASSISTANT ENGINEER  
 LSGD (LID & EW) SECTION  
 VALAPAD GRAMAPANCHAYATH

